

February 9, 2012

## SAFETY RECALL NOTICE

Dear Valued Toyo Tires Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyo Tires has decided that a defect which relates to motor vehicle safety exists in certain Toyo® Extensa® A/S tires as specified below. Toyo Tires is recalling approximately 68,763 of the tires in the United States.

We are conducting this campaign to ensure that you are completely satisfied with your Toyo product.

### RECALL TIRES

The following tires are subject to this recall campaign:

| Brand, Model       | Size (Load Index/Speed Rating) | Tire Identification Number (TIN)   |
|--------------------|--------------------------------|------------------------------------|
| Toyo® Extensa® A/S | P225/60R16 97T                 | 73A6H2N3809 through<br>73A6H2N4410 |

These tires were manufactured at the Toyo Tires plant in Georgia, U.S.A. during the period from the 38th week of 2009 through the 44th week of 2010. The tires can be identified on the sidewall by the "Made in U.S.A." mark and the last four digits of the Tire Identification Number (TIN), ranging from 3809 to 4410. The TIN can be found after the letters "DOT" on the tire sidewall.

Tires manufactured before or after this period are not being recalled, nor are tires with the "Made in Japan" or "Made in China" mark.

The photographs below will assist you in locating the tire information on the sidewall.

**Tire model name: "EXTENSA A/S"**



**"MADE IN U.S.A."**



**The DOT serial number follows the "DOT" symbol (for illustrative purposes only):**



